


Maule Aircraft Corporation

6780 BROOKLYN ROAD

JACKSON, MICHIGAN - 49201

PHONE KE 6-8642
AREA CODE 517

August 25, 1964

Service Letter No. 5
Model Effected: M-4
Serial Numbers Effected 68 to 77

Dear Customer:

It will be required to add a forward seat stop to your front seats as outlined below:

1. Drill a 3/16" diameter hole in the forward seat guide 1/4" from the rear and on it's center line, on the left side of the seat.
2. Install the AN3-3 bolt and AN365-1032 nut with the bolt pointing upward in this hole.

This installation should be done as soon as possible and will you please notify us by filling out the enclosed post card when this is accomplished.

Very truly yours,

MAULE AIRCRAFT CORPORATION

Daniel L. Yother

Daniel L. Yother
Project Engineer

DLY/jh

Enclosures

MAULE AEROSPACE TECHNOLOGY, INC.

SERVICE LETTER #5 - COMPLIANCE RECORD

Airplane Serial Number _____

Airplane Registration Number _____

The following action was taken with respect to this Service Letter:



Service Letter #5 completed

Certified by _____

(Signature)

(Printed name)

Title _____

(Owner, A&P, IA, etc.)

Date performed _____

In an effort to keep our mailing list current for sending Service Letters, Service Bullatins, etc., please fill in the following:

Owner's name _____

Owner's address _____

Mail this Compliance Record to: Maule Aerospace Technology, Inc.
Engineering Records
Spence Field
Moultrie, GA 31768