

FAA App'd:

## SERVICE LETTER NO. 61

Page 1 of 2 Date: 7/8/99

**SUBJECT:** Attach Hardware for all doors.

AIRPLANES AFFECTED: All Maule models manufactured before 6/99.

**BACKGROUND:** The door hinge bolt has always been retained by an elastic stop nut. Recently the upper pilot's door hinge separated on a Maule M-5 in flight. The upper hinge bolt was missing after a safe landing so the exact cause of the failure is not known.

<u>COMPLIANCE:</u> It is <u>mandatory</u> to inspect all door hinge bolts for security next preflight inspection and all subsequent preflight inspections. Replacement of existing elastic stop nuts with castellated nuts and cotter pins is mandatory at next annual inspection.

**STATUS:** This Service Letter should be considered an early warning of a potential safety of flight problem. New production airplanes are now using castellated nuts and cotter pins.

### **ACTION TO BE TAKEN AND MATERIAL REQUIRED:**

- Replace hinge nuts and bolts of all doors as follows:
  - a. Remove existing nuts and bolts on all doors if AN365 elastic stop nuts are installed and replace with the following:

The following parts are available from Maule, if required:

AN3-3 or AN3C3 (Corrosion Resistant) 8 ea. Bolt
AN310-3 or AN310C3 (Corrosion Resistant) 8 ea. Nut
AN380-2-2 or AN381-2-2/MS24665-151 (Corrosion Resistant) 8 ea. Cotter Pin

#### REPLACEMENT INSTRUCTIONS:

- Remove existing bolt and nut one at a time.
- Lubricate new drilled bolt and inside faces of hinge brackets with LPS-3, Zep super lubricant or equivalent. Insert bolt downward.
- Install castellated nut and tighten just to remove end play.
- 4) Insert cotter pin and bend tight against nut so as not to leave a sharp projection.

Note: Page 2 is the Service Letter Compliance Record Sheet and is to be completed and returned to Maule engineering records.

ITS PERFORMANCE THAT COUNTS! 2099 Georgia Hwy. 133 South~Moultrie, GA 31768 Tel: 912-985-2045~Fax: 912-890-2402



Page 2 of 2 7/8/99

# SERVICE LETTER NO. 61

### **COMPLIANCE RECORD SHEET**

Aircraft Model			
Aircraft Serial No			
Action taken (CHECK IF COMPLETED):			
( ) Service Letter No. 61 is complied with.			
Owner's Name			
Owner's Address			
City	State	Zip	
Certified bySignature	Title		
Signature  Date performed	Own	ner, A & P. IA. Etc.	
NOTE: If you no longer own this aircraft, please f erator and notify the factory of address/ o rial number, current owner's name and ad address below.	wnership correc	ctions. Include aircraft model,	se-
NEW Owner's Name		AV.	
NEW Owner's Address		e.	-
City	State	Zip	
Please mail this Compliance Record to: Maule Ai Highway 133 South ~ Moultrie, GA 31768 USA	ir, Inc. ~ Engine	ering Records ~ 2099 Georgia	

ITS PERFORMANCE THAT COUNTS! 2099 Georgia Hwy. 133 South~Moultrie, GA 31768 Tel: 912-985-2045~Fax: 912-890-2402